



TractionCOTETM **Detailed Application Instructions**

Tools Required:

Cleaning: 1x ~5 gallon pail – clean

Cleaning: Extraction tool/wet vac (recommended)

or mop/sponge mop or squeegee

Cleaning: Brush/Deck Brush

Application: Low nap roller/kit (recommended) / Bristle Brush or

Airless Sprayer

Read all instructions before starting application process.*

PRE-APPLICATION:

Make sure surface to be treated is clean, free of any dirt, debris, grease, oils or other contaminants. DO NOT APPLY at temperatures below 50°F or above 90°F. TEST a small hidden area or extra piece to ensure adhesion and review for any adverse effects.

Application Directions

- 1. CLEAN, RINSE & DRY SURFACE to remove all dirt and soap residue. Allow to dry.
- 2. SHAKE WELL and POUR into supplied paint tray.
- 3. **ROLL** onto surface with supplied roller, using smooth overlapping strokes. Roll out to even, flat finish.
- 4. **ALLOW TO DRY** approximately 30 min. Apply 2nd coat, if desired. Do not use tub for 12 hrs.

APPLICATION CLEAN UP: Clean spills with soap and warm water, immediately, do not allow to dry.

ROUTINE CLEANING: Clean with mild soap and water. DO NOT USE abrasive cleaners or pads

REMOVAL: TractionCote TM can be removed with isopropyl alcohol or any commercial paint stripper.

Do not walk on for 2 hrs. Full cure in 24-48 hours before heavy use.

Post application:

Surface Solutions TractionWash[™] is recommended for routine cleaning (@ 1:20 dilution).

ReApply approx. every 3-6 mos or as wear patterns develop. Actual effective life will vary depending on type, frequency and weight/abrasion and traffic patterns.



Company Profile:

Surface Solutions, LLC

Industry:

Surface Engineering Surface Consulting DCOF Testing/Auditing Slip Resistant Treatments Anti-Graffiti Treatments

Website:

www.totalsurfacesolution.com

Corporate Address:

515 Valley St, suite 130 Maplewood, NJ 07040

Contact:

info@totalsurfacesolution.com 888-842-3356